

DIGITAL PANEL METERS
programmable $\pm 10\ 000$ points


DIGINORM



DGN 75

User handbook

Applies for all devices version 06.xx

 **KLAY-INSTRUMENTS**

■ Summary

1 . INTRODUCTION	p2
2 . SPACE REQUIREMENTS	p3
3 . CONNECTIONS	p4
4 . PROGRAMMING	p5
4.1 Communicating with the instrument	p5
4.2 Find your way through programming	p5
4.3 Main menu	p5
4.4 Programming menu	p6
4.4.1 - Input programming	p6
<i>a / Process signals</i>	p6
<i>b / Temperature signals</i>	p7
<i>c / Resistive sensors</i>	p7
4.4.2 - Display programming	p8
4.5 Input features and programming limits	p11
4.5.1 - Current input	p11
4.5.2 - Voltage input	p12
4.5.3 - Temperature input	p12
4.5.4 - Resistance and potentiometer inputs	p13
4.5.5 - LOGIC inputs	p13
4.6 Output features and programming limits	p13
4.6.1 - Analogue output	p13
4.6.2 - Digital output	p14
4.6.3 - Relay outputs	p14
4.6.4 - Safeties	p15
4.6.5 - Display features	p16
4.7 Configuration reading	p17
4.8 Access code	p17
4.9 Programming of a new access code	p18

■ Summary

4.10 Functions accessible in the main menu	p18
4.10.1 - Display simulation	p18
4.10.2 - Analogue output simulation	p18
4.10.3 - Menu CLEAR :	
Erase recorded alarms	p18
4.10.4 - Menu CLr.tA :	
Suppress programmed tare	p19
5 . DIRECT FUNCTIONS FROM DISPLAY	p19
5.1 Functions accessible by pressing 1 key	p19
<i>a / Display of lowest value</i>	p19
<i>b / Display of highest value</i>	p19
<i>c / Erasing of lowest and highest values</i>	p19
5.2 Functions accessible by pressing several keys	p20
5.2.1 - Display shifting	p20
5.2.2 - Visualise direct measure	p20
5.2.3 - Visualise and adjust alarm setpoints	p21
5.2.4 - Set tare (process input only)	p21
6 . ERROR MESSAGES	p21
7 . GENERAL WARRANTY TERMS	p21
8 . LEXIQUE	p21
9 . ANNEXE : MODBUS	p25
9.1 Table of modbus adresses	p25
9.2 Description of born modbus functions	p26
9.3 Reading in double integer format	p26
9.4 CRC 16 calculation algorithm	p27

1. INTRODUCTION

The series **DGN 75** offers a whole range of high accuracy programmable panel meters. Each instrument is equipped on its front face with a five 14mm high red digits display, whose brightness suits applications in industrial control rooms perfectly.

They enable display, control and transmission of data from any measurable magnitude.

- The **DGN 75 U** (Process Input) counts as standard :

A DC current or voltage input

Bidirectionnal $\pm 100\text{mV}$, $\pm 1\text{V}$, $\pm 10\text{V}$, $\pm 300\text{V}$, $\pm 20\text{mA}$.

- Accuracy : 0,05 % of full scale at $+25^\circ\text{C}$
Tehrmic drift $< 150\text{ppm}/^\circ\text{C}$
- Measurable scale overstepping from -5 % to +5%
- Scale factor programmable
- Enlarging effect - Square root extraction
- Special 20 point linearisation
- Supply for 2 or 3 wire sensor 26 V_{DC} ($\pm 15\%$) -25 mA protected from short circuits

- The **DGN 75 T** (Temperature Input) counts as standard :

Either a thermocouple input :

(J, K, N, S, B, W5, T, R, E, W, W3, L)

- Accuracy : 0,1% of full scale at $+25^\circ\text{C}$,
or $25\mu\text{V}$ typical ($50\mu\text{V}$ max.)
- Thermic drift $< 150\text{ppm}/^\circ\text{C}$
CJC efficiency : $< 0,03^\circ\text{C}/^\circ\text{C} \pm 0,5^\circ\text{C}$ from -5°C to $+55^\circ\text{C}$

Or a sensor input : Pt 100 Ω , Ni 100 Ω

- Line resistance influence in 3 wire measure included in grade for $0 < R_I < 25\Omega$
- Measure of Δ Pt100 2 wires from -200°C to $+270^\circ\text{C}$ ($0 < R_I < 10\Omega$)
(R max. 400Ω)
- Max. measure current : $250\mu\text{A}$
- Accuracy : 0,1% of full scale at $+25^\circ\text{C}$
- Tehrmic drift $< 150\text{ppm}/^\circ\text{C}$.

- **The DGN 75 M** (Inputs Process, temperature, resistance and potentiometer)

(See DGN 75 U and DGN 75 T features on left hand column)

Resistive sensors : calibers 0-400 Ω and 0-2 k Ω (0-8 k Ω option)

- Accuracy : 0,1% for calibers 0-400 Ω and 0-8 k Ω and
0,5% for caliber 0-2 k Ω (of full scale at $+25^\circ\text{C}$)
- Tehrmic drift $< 150\text{ppm}/^\circ\text{C}$

Potentiometers : from 100 Ω to 10 k Ω

- Accuracy : 0,1% of full scale at $+25^\circ\text{C}$
- Tehrmic drift $< 150\text{ppm}/^\circ\text{C}$

AVAILABLE OPTIONS : (specify on order)

Insulated analogue output : A

Active or passive current, or voltage.

Programmable scale ratio with enlarging effect.

Relay output : R or R4

2 or 4 relays : mode setpoint or mode window.

Recording of alarms.

Temporisation and hysteresis adjustable on each setpoint.

Alarm messages

Insulated digital output : N

RS 485 2 wires, protocole MODBUS-JBUS.

LOGIC input 2 insulated LOGIC inputs with programmable functions

Display locking,

Decimal point moving,

Tare function,

min. and max. zero reset

Bargraph :

(display 16 leds) : B

Enables fast evaluation of the measured value variations.

Programmable scale factor

General features


- Sampling time : 100 ms
- Input impedance $\geq 1 \text{ M}\Omega$ for voltage inputs
Drop 0,9 V max. for current input
- Common mode rejection rate : 130 dB
Serial mode rejection rate 70 dB 50/60 Hz
- Zero drift compensation and self calibration
- Insulation : Input / power supply : 2,5 kV eff. 50Hz-1min
Input / Output : 2,5 kV eff. 50Hz-1min
- **Power Supply** : *(specify on order)*
2 Versions : High Voltage or Low Voltage
High Voltage : 90...270 VAC and 88 ...350 VDC 50/60/400 Hz
Low Voltage : 20...53 VAC and 20...75 VDC 50/60/400 Hz
- **Power draw** : 5 W max. 8 VA max.
- **Complies** with standards EN 50081-2 on emission and EN 50082-2;
on immunity (industrial environment)
EN 61000-4-2 level 3, EN 61000-4-3 level 3,
EN 61000-4-4 level 4, EN 61000-4-6 level 3.
Marked CE according to directive CEM 89-336

2. SPACE REQUIREMENTS

Case dimensions : (including terminals)


96 x 48 x 124 mm

Holding panel
max. thickness 30



Panel mounting

Cut out 44 x 91 mm



Protection :

Front face : IP 65

Case : IP20

Terminals : IP 20

Case :

Self-extinguishing in black
UL 94 V0 ABS.

Connectors plug-off connectors on
rear face for screwed connections
(2,5mm², flexible or rigid)



Display : $\pm 10\,000$ points (14 mm)
Electroluminescent red (green as option)
4 alarm Leds
+ 4 leds with programmable functions

-10 000/+100 000 points (14 mm)
(as option)


-2 000 / +10 000 points (20 mm)
(consult with us)

3. CONNECTIONS

INPUTS




Location of terminals
(view from case rear face)





OUTPUTS (options)


VOLTAGE
CURRENT PASSIVE



ACTIVE CURRENT




DATA LINK



4. PROGRAMMING

4.1 Communicate with the instrument

Several functions based on the measuring are available :



You can access further functions by pressing several keys simultaneously :

- + Setting of down scale display; (see p20)
- + Setting of full scale display; (see p20)
- + Visualise direct measure ; (see p20)
- + Visualise and adjust alarm setpoints; (see p21)
- + Set tare (except temperature inputs see p21)

Reading convention :

- Move through main menu
- Revert to previous menu
- Flashing display : awaiting validation or setting
- Alternate information display

Entering a parameter :

- Start by increasing or decreasing and the 1st digit and the sign : from -9 to +9.
 - The 2 nd from 0 to 9.
 - The 3 rd from 0 to 9.
 - The 4 th from 0 to 9.
- Between each entering, validate the digit by pressing

4.2 Find your way through programming

Dialogue is ensured by 4 keys located on the front face.



Move through menus to the bottom, or decrease displayed value



Move through menus to the top, or increase displayed value



Exit a sub-menu to access next menu / access programming exit menu




Validate displayed parameter, or access a sub-menu

Note : In mode programming, the instrument will automatically revert to measure with the former configuration, if no key is pressed during 1min.


4.3 Main menu

scroll menus
 menus

vertical moving



4.4 Programming menu *(according to options)*



Note :

⇒ Press key $\textcircled{M}$ to revert to menu **SAuE**

⇒ In mode programming, the instrument will automatically revert to measure with the former configuration if no key is pressed during 1min.


Note :

Press key $\textcircled{M}$ to go on to next menu ∇ Move through menus / choice

- | | |
|--|---|
| $\textcircled{M}$ Exit / Menu access | $\triangle$ Move to the top / Increase |
| ∇ Move to the bottom / decrease | $\textcircled{\curvearrowright}$ Validation / Vertical move |

4.4.1 Input programming

a. Process signals



Note :

Press key $\textcircled{M}$ to revert to menu **diSPL.**


InPut

DGN 75 U
DGN 75 M

b. Temperature signals

DGN 75 T
DGN 75 M


process
signals



c. Resistive sensors

temperature signals
process signals

DGN 75 M



Note :

Press key to go on to next menu



Move through menus / choice



Exit / Menu access



Move to the top / Increase



Move to the bottom / decrease



Validation / Vertical move

Note :

Press key to revert to menu **dISPL.**


* cold junction compensation, except thermocouple B, which is only in external CJC.




Move through menus / choice



4.4.2 Display programming



Option analogue output



See also output features p13

Note :

Press key **(M)** to go on to next menu

(V) Move through menus / choice



(M) Exit / Menu access

(A) Move to the top / Increase

(V) Move to the bottom / decrease

(J) Validation / Vertical move

Communication parameters



See also LOGIC input features p13

Note :

Press key **M** to go on to next menu



Move through menus / choice



Exit / Menu access



Move to the top / Increase






Move to the bottom / decrease




Validation / Vertical move

Option output 2 or 4 relays





Exit programming with or without saving



Note : Exit of programming mode saving configuration (**SAVE, YES**) will automatically reset to zero tare, min. and max. as well as alarm recording.

In case of decimal point location modification or resolution modification (for temperature), the instrument will propose after **SAVE YES** all parameters with decimal point that have not been modified (see p8)

4.5 Input features and programming limits

4.5.1 Current input

• Linear :

Features

Caliber	Display resolution	Input resolution	Accuracy
from -20 to +20mA	± 1 digit	14 bits	0,05% of measure range

Input measurable limits : -22 to 22 mA

• Not linear :

Square root extraction

Note : Function square root tends to amplify the input signal background noise when it gets near 0.

To avoid drifts caused by this noise, just programme a cut-off value (in display points).

– If display full scale > display down scale and if display ≤ cut off value then it is maintained at down scale.

– If display full scale < display down scale and if display ≥ cut off value then it is maintained at down scale.

Special linearisation :

For special applications, such as volume measure, the meter can record an unlinear curve programmable in X and in Y.

The curve resulting from your equation can be replaced by a sequence of linear segments with a maximum of 20 points (19 segments).

Note : The values of abscisses (x) must be entered increasing d.in < A01 value < A02 value...< F.in.

Example :

For a cylindric layed tank, measuring 1 meter in height (h) and 1 meter in length (l); a 0-20 mA linear sensor measures the liquid surface line height :


Meter input : height h

0 meter -> 0 mA (tank empty)

1 meter -> 20 mA (tank full)

with $\cos \beta/2 = (R - h)/R$

$\sin \beta/2 = C/2R$



Meter display :

Empty tank volume d.diSP = 0.000

Full tank volume F.diSP = 0.785

$$\text{Volume} = L [\pi R^2 \beta/360 - C(R-h)/2]$$

Say a 10 equally long segments curve :

Measure span / number of segments = 20 mA / 10 = 2 mA segment length. For 10 segments nb = 9 (11 points to be programmed, with d.in and F.in).

Input mA	Height m	Degree	Chord m	Volume m³	Outpts in mA
d.in 0	0.0	0.00	0.00	d.diSP 0.000	00.00
A01 2	0.1	73.74	0.60	B01 0.041	01.04
A02 4	0.2	106.26	0.80	B02 0.112	02.85
A03 6	0.3	132.84	0.92	B03 0.198	05.04
A04 8	0.4	156.93	0.98	B04 0.293	07.47
A05 10	0.5	180.00	1.00	B05 0.393	10.00
A06 12	0.6	203.07	0.98	B06 0.492	12.54
A07 14	0.7	227.16	0.92	B07 0.587	14.96
A08 16	0.8	253.74	0.70	B08 0.674	17.17
A09 18	0.9	286.76	0.60	B09 0.745	18.98
F.in 20	1.0	360.00	0.00	F.diSP 0.785	20.00


Programming :

d.in = 0 mA F.in = 20 mA

nb = 9

d.disp = 0,000 m³ F.disp = 0,785 m³

Programming from A01 to A09 and from B01 to B09 : see table.



4.5.2 Voltage input

U

• Linear : Features

Caliber	Display resolution	Input resolution	Accuracy
-100 to +100 mV -1 to +1 V -10 to +10 V -300 à 300 V	± 1 digit	14 bits	0,05% of measure span

Measurable limits : -5% to +5%

Example for caliber 1V : -1,1V at +1,1V

• Not linear : (see p11)

4.5.3 Temperature input

Pt 100

dPt

ni 100

• Resistor sensor

Pt 100

Platinum probe RTD 100 Ω in 3 wire system

dPt

Delta RTD 100 2 wire measure

ni 100

Nickel probe ni 100 Ω

Sensor type	Measurable input limits	Accuracy (EM: measure span)
Pt 100	-200 / 850 °C -328 / 1562 °F	* ± 0,1% of EM
ni 100	-60 / 260 °C -76 / 500 °F	± 0,1% of EM
Delta Pt 100	-200 / 270 °C -328 / 518 °F	± 0,1% of EM

* The line resistance influence $0 < R_l < 25 \Omega$ is included in the accuracy rating.

• Thermocouple

Type : J, K, N, S, B, W5, T, R, E, W, W3, L

Cold junction compensation efficiency :
0,03% / °C ±0,5% from -5°C to +55°C

Cold junction compensation CJC

Internal CJC-I

External CJC-E

Programmable from -10°C to 60°C
+14°F to 140°F

Thermocouple		Measurable input limits		Acc. in mea. span %*
		°C	°F	
tc-jj	J	-160 / 1200°C	-256 / 2192°F	0,1 %
tc-KA	K	-270 / 1370°C	-454 / 2498°F	0,1 %
tc-m	N	0 / 1300°C	32 / 2372°F	0,1 %
tc-5	S	-50 / 1770°C	-58 / 3218°F	0,1 %
tc-lb	B	200 / 1820°C	392 / 3308°F	0,1 %
tc-55	W5	0 / 2300°C	32 / 4172°F	0,1 %
tc-tt	T	-270 / 410°C	-454 / 770°F	0,1 %
tc-rr	R	-50 / 1770°C	-58 / 3218°F	0,1 %
tc-E	E	-120 / 1000°C	-184 / 1832°F	0,1 %
tc-C	W	1000 / 2300°C	1832 / 4172°F	0,1 %
tc-33	W3	0 / 2480°C	32 / 4496°F	0,1 %
tc-lL	L	-150 / 910°C	-238 / 1670°F	0,1 %

* or 10µV typical (20µV max.) for R, S, B
25µV typical (50µV max.) on the others

4.5.4 Input resistance and potentiometer

• Resistance

Caliber	Measurable input limits	Measure span accuracy
0 / 400 Ω	0 / 440 Ω	0,1%
0 / 2000 Ω	0 / 2200 Ω	0,5%
0 / 8 KΩ (option)	0 / 8,8 KΩ	0,1%

• Potentiometer :

Caliber	Measure span accuracy
from 100Ω to 10 KΩ	0,1%

4.5.5 LOGIC inputs (optional)

- Board of 2 LOGIC Inputs : Input signal 24 Vdc


Possible functions :

HoLd Holds display in case function LOGIC is enabled
Display and analogue output remain still in case of input signal variation. The relays will continue to react to the input signal.

CLr.M Reset min. and max. to zero. Enabling function LOGIC will reset min. and max. to zero

tArE Enable function tare.
The meter passes in mode tare, tare being the display value present at the moment of enabling.

Point Function decimal point moving

 In case function LOGIC is enabled, the decimal point places itself like programmed.

4.6 Output features and programming limits

4.6.1 Analogue output **Out.MA** or **Out.U**

Current output 0/4-20mA active or passive (Vmax.=30Vdc) or voltage output 0-10V

- Accuracy 0,1 % in relation to display (at +25°C)
- Residual drift ≤ 0,2%
- Admissible load $0\Omega \leq R_c \leq 500\Omega$ (current)
 $R_c \geq 2\text{ k}\Omega$ (voltage)
- Scale ratio programmable with enlarging effect
- Response time : 40 ms in relation to display

d.out Analogue output down scale (eg 04.00 (4mA))

F.out Analogue output full scale (eg 20.00 (20mA))

dO.diS Display value corresponding to output down scale

FO.diS Display value corresponding to full scale value

In mode measure, the analogue output can not overstep 10% of the greatest of the 2 values : d.out and F.out

4.6.2 Digital output :

- Data link RS485 (2 wires)
- Protocoles **MODBUS-JBUS** data format : integer and double integer
- One transmission format only :
 - 1 start bit
 - 8 parityless bits
 - 1 stop bit

SLAuE	Slave number included between 1 and 255
bAud	Baud rate included between 1200 and 19200 bauds
dELAY	Delay to be counted before any answer pattern

Table of modbus addresses, functions used, see annexe p25

4.6.3 Relay outputs :

2 relay outputs rEL.1 rEL.2
or 4 relay outputs rEL.1 rEL.2 rEL.3 rEL.4


- Hysteresis programmable independently in the display unit
- Temporisation programmable independently from 0 to 25 s in 0,1s. increases
- NO-NC contact 8 A - 250 V on resistive load

Enable or disable alarm x AL.X

On	The state of relay x depends on the entered programming
OFF	Relay x remains still

Choice of function mode : ModE.x


• Mode setpoint



Legend :

ON coil supplied
OFF coil not supplied

• Mode window



Choose state of the Led associated with the relay LEdx


The Led indicates the state of alarm

On	The Led is lit when relay enabled (coil supplied)
OFF	The Led is still when relay enabled (coil supplied)


HYS.t.x Adjust hysteresis in display points.

The hysteresis is enabled as the Led passes from lit to still, i.e. when alarm stops, as the Led represents the alarm state.

• Mode setpoint



• Mode window



• **Alarm delay** tIME.x

The relay delay is adjustable from 000.0 to 025.0s., in 0,1s. increases. It is active on enabling and disabling.

• **Alarm recording** MEM.x

Allows alarm recording when setpoint is passed. As measure comes back below the alarm setpoint, the relay remains enabled and the Led flashes to warn the user that the setpoint has been passed (to set alarm recording to zero see menu CLEAR p18).

Note : Return from programming mode saving configuration will reset alarm recordings to zero.

• **Display of alarm messages** MESSx

You can have the display to show a programmed alarm message alternating with measure. The message will appear only as alarm is ON, i.e. when the associated Led is lit.

• **Setting of setpoints** : You have 2 ways to adjust setpoints.

- either in mode programming entering the correct access code
- or by pressing simultaneously M and △ if access to fast entering has been authorized during code programming (see p17)

4.6.4 Safeties :

• **Self diagnosis** : diAG

The meter permanently watches any drifts of its components that may surge. The self-diagnosis serves to warn the user from abnormal increases of these drifts before they provoke false measures.

The error self diagnosis information can be transmitted :

- On the display : An error will appear alternating with measure; an error code is entered and can be read in menu About (see p17)

Coding :

- 1 : Programming error
- 2 : Gain error
- 4 : Offset error
- 8 : Input calibration error
- 16 : Output calibration error
- 32 : Cold Junction Compensation error

If the instrument detects an offset error for instance (4) and a gain error (2) the **error code value will be 6** (4+2).

• On relays :

OFF	No influence of an error self diagnosis on the relay
LO	Relay disabled (coil not supplied) in case of error self-diagnosis
HI	Relay enabled (coil supplied) in case of error self-diagnosis

Note : The led is still or lit according to its programming in menu rELAY.

• On the analogue output

If a return value is programmed

Value included between : 0 and 22 mA (current output)
or 0 and 11 V (voltage output)

• **Sensor rupture** ruPt

The sensor rupture can be detected on inputs mV, CT, Pt100, Ni100, ΔPT100, resistance (0-400Ω), and current if down and full scale > 3,5 mA.

The sensor rupture information can be transmitted :

• On the relay

OFF	No influence of sensor rupture on the relay
LO	Relay disabled (coil not supplied) in case of sensor rupture
HI	Relay enabled (coil supplied) in case of sensor rupture

Note : The led is still or lit according to its programming in menu rELAY.

• On the analogue output

If a return value is programmed

Value included between : 0 and 22 mA (current output)
or 0 and 11 V (voltage output)

• On the display : Message OPEN

Note : The sensor rupture detection has priority on the self diagnosis.

• **Disconnect sensor rupture** (If input mV or temperature)

You can disconnect sensor rupture, in order not to disturb some calibrators that may be sensitive to the rupture detection current :

In menu SECU :

CAPt	Disconnect sensor rupture, or not
On	Not disconnect sensor rupture
OFF	Disconnect sensor rupture

4.6.5 Display features :

- Point** Placing of decimal point for inputs other than temperature
- rESOL** Display resolution for temperature inputs **0,1°** or **1°**
- d.diSP** Display corresponding to input down scale (except temperature input)
- F.diSP** Display corresponding to input full scale (except temperature input)
- Cut.oF** Only for inputs process, resistance, potentiometer, expressed in display points.

– If display full scale > display down scale and if display ≤ cut off value then it is maintained at down scale.

– If display full scale < display down scale and if display ≥ cut off value then it is maintained at down scale.

• Response time :

intEG Digital filtering integration indice :
Programmable from 0 to 10; to be used in case of unsteady input signal.

intEG	0	1	2	3	4	5
Typical response time at 90%	120 ms	400 ms	600 ms	1 s	1,4 s	2 s
	6	7	8	9	10	
	3 s	5 s	7,5 s	10 s	15 s	

To have the max. response time, add 240 ms.

Note : For the analogue output response time, you have to add 40ms to values given in this table.

For the relays : you have to add the delay programmed on the alarms.

• Adjust digits brightness **br.diG**

11111 Lowest brightness **44444** Highest brightness

• Adjust brightness of bargraph and Leds **br.bAr**

11111 Lowest brightness **44444** Highest brightness

The brightness level is visualised directly on Leds 5 to 8 and on the bargraph.

Caution : during adjusting, the 4 Leds and the bargraph no longer represent measure, like also in mode reading.

• Inhibition of last digit (LSB) **L.dIG**

In the programming mode, menu L.dIG allows to suppress the last digit of display, the latter being enforced to 0 if OFF is enabled.

• Erasing of insignificant zeros **nuLL**

nuLL = **YES** Erases insignificant left hand zeros.

Eg : Display value 0015

nuLL = **no** Display 0015
= **YES** Display 15

Eg : Display value 00.15

nuLL = **no** Display 00.15
= **YES** Display 0.15

• Bargraph display factor (option bargraph only)

d.bArG Display corresponding to still bargraph (0%)

F.bArG Display corresponding to a fully lit bargraph (100%)

In case of overstepping, the bargraph starts to flash. A sensor rupture is indicated on the bargraph by lighting of one Led out of two.

• Programming of Leds 5 to 8

Programming of Led 5 **LEd5**

no Led still (no function associated)
tArE Led 5 indicates that the instrument is in mode tare
tor ! Led 5 is lit when LOGIC input 1 is active

Programming of Led 6 **LEd6**

no Led still (no function associated)
tor 2 Led 6 is lit when LOGIC input 2 is active


Programming of Led 7 LEd7

no	Led still (no function associated)
rS	Led 7 is lit during instrument response

Programming of Led 8 LEd8

no	Led still (no function associated)
AdJuS.	Led 8 is lit when a shifting of display down and/or full scale has been entered (see p20) (temperature inputs only)

4.7 Configuration reading rEAd



In each reading submenu, press and to move, and to visualise parameters.

If no key is pressed during 20 s., the instrument will revert to measure display.

Submenu

XXXXX
1 2 3 4 5.

X1 : - : No analogue output
A : Analogue output

X2 X3 : - - : No relay output
r- : Output 2 relays
r4 : Output 4 relays


X4 : - : No RS output
n : RS output

X5 - : No LOGIC input
t : 2 LOGIC inputs

(.) : decimal point still :
no bargraph

“.” : decimal point lit :
option bargraph

About




4.8 Access code

An access code adjustable from 0000 to 9999 serves to protect the meter and the setpoints from unauthorized programming, and to lock access to some functions.

0 0 0 0				Factory code
x	x	x	x	
0 to 5	6 to 9			Access to display shifting
0 to 5	6 to 9			No access
0 to 5	6 to 9			Access to display and output simulations
0 to 5	6 to 9			No access
0 to 5	6 to 9			Access to function “tare” (except temperature inputs)
0 to 5	6 to 9			No access
0 to 5	6 to 9			Access to fast entering of alarm setpoints
0 to 5	6 to 9			No access

4.9 Programming of a new access code




Reminder : If no key is pressed during 1 min, the instrument will revert to measure display.

4.10 Functions accessible in the main menu

4.10.1 Display simulation

(accessible according to programmed access code and if option relays or analogue output)


Display can be simulated with the meter in order to validate the analogue output and relay outputs configuration in the system.



Note : During simulation, the instrument no longer measures, the analogue and the relay outputs react according to entered display value. If alarm messages have been programmed, they can appear during simulation.

4.10.2 Analogue output simulation (mode generator)

(accessible according to programmed access code and if option analogue output)




Note : During simulation, the instrument goes on measuring, only the analogue output no longer reacts to measure.

4.10.3 Menu **CLEAR** : Erasing of recorded alarms

If function alarm recording has been programmed :
After passing the setpoint, the relay state is recorded.

If the setpoint is passed in the opposite way, the relay does not change state and the corresponding Led starts to flash.
To come back to the normal state (Led not flashing and relay in the correct state, use menu **CLEAR**).




Reminder : If no key is pressed during 20 s., the instrument will resume measure display.

Note : Exit from programming mode saving configuration will reset recorded alarms to zero.

4.10.4 Menu **CLr.tA** : **to suppress programmed tare**

(accessible according to programmed access code)




Reminder : If no key is pressed during 20 s., the instrument will resume measure display.


5. FUNCTIONS DIRECT from DISPLAY

5.1 Functions that require pressing only 1 key :


a / Display min. value



b/ Display max. value



c / Erase maximum and minimum values



the instrument resumes measure display.

Reminder : If no key is pressed during 20 s., the instrument will resume measure display.

Note : Exit from programming mode saving configuration will reset min. and max. values to zero.

5.2 Functions that require pressing several keys :

5.2.1 Display shifting

(accessible according to programmed access code)

⬆ ⬇ Shift display down scale (AdJ.Lo)

⬇ ⬆ Shift display full scale (AdJ.Hi)

After injecting an input signal corresponding to down (or full) display scale, press simultaneously on keys ⬆ and ⬇ (or ⬇ and ⬆). Message AdJ.Lo (AdJ.Hi) appear alternating with the value, to indicate you are in the adjusting menu.

By pressing ⬆ and ⬇ you can also decrease or increase the down (or full) display scale.

If you keep pressing during 3s. on ⬆ or ⬇ you will have access to fast decreasing or increasing of the display value.

Press ⬇ to validate the shifting. Once shiftings are validated, the shifted input will keep this shifting even if set out of tension.

Pressing ⬆ (or no pressing during 20 s) will induce return to measure display without modification.

• Case of a process, resistance or potentiometer input

The instrument will then readjust its scale factor and its display factor in order to obtain the required result on the display.

• Case of a temperature input

On a temperature input; if one of the two settings is performed : this corresponds to an offset, which means all points will be shifted by an equal quantity.


However, if both settings are performed, slope and offset will have to be corrected, in order to obtain the required result.

example :

Say an RTD 100 input for 0°C, the obtained display is -000.3
At 500°C the obtained display is 0500.2. To correct this display, you have to shift the display down scale by 3 points to obtain 000.0 and shift the display full scale by -2 points to obtain 0500.0.

note : Only for **temperature inputs :**

From menu rEAd, the performed scale shiftings can be visualised in sub-menu InPut :



Suppress input shifting :

(Case of temperature input only)

Menu AdJuS. in mode programming of a temperature input allows to suppress or not suppress the entered shift.

no : the instrument returns to the settings it had on factory exit

Yes : the instrument takes new entered settings (offset and/or slope) into account.

5.2.2 Direct measure visualising

Press ⬇ and ⬆ to visualise the signal directly, without processing : scale factor, square root, linearisation

- in mV, V or mA for process inputs,
- in mV for thermocouple input,
- in Ω for input Pt100, Ni100,
- in Ω for resistance input,
- in percentage for potentiometer input,
- hot sensor temperature for Δ Pt100 input.

5.2.3 Visualisation and setting of alarm setpoints

Option 2 or 4 relays

Setting of setpoints : 2 ways are possible to adjust setpoints.

- either in mode programming entering the correct access safety code (see p17)
- or pressing simultaneously on  and 

The display will then show message SP.x ou SPx.x alternating with the corresponding setpoint value.

To access the various setpoint values, press  and .

You can then modify the setpoints (if access code < 6000 (see p17)). by pressing 

Once the setpoint is adjusted, press  to come back to the setpoint reading menu.

Once all setpoints are adjusted, just press  and the meter will revert to mode measure, taking the new values into account.

If no key is pressed during 60 s., the meter reverts to measure display without setpoint value modification.

5.2.4 Tare setting (except temperature inputs) (accessible according to programmed access code)

Press  and  to enforce the display at display down scale for the input signal 

Note : The tare will not be recorded in case of power supply cut.
To suppress the tare, validate menu  in the main menu p19
Exit from programming mode saving the configuration will reset the tare to zero.

6. ERROR MESSAGES

	Measure overstepping		Electrical lower or upper input overstepping
	Sensor rupture		Overstepping of displayable value
	Value set out of range		Error self-diagnosis (see p15)

7. GENERAL WARRANTY TERMS

WARRANTY applying and duration

The company guarantees this instrument for a duration of 1 year from any design or manufacturing defects, under normal operating conditions.

Intervention terms * : The processing out of warranty will be subject to acceptance of a proposal. The products will have to be returned at the customer's expense to the company, who will return them at its cost after processing. Without a written agreement on the repair quotation within 30 days, the products will not be kept.

** Details and complete warranty terms available on request.*

8. LEXIQUE

Messages shown by the meter in mode programming and/or reading

General access

	Access to parameter reading
	Access to programming of input and output parameters
	Code for access to programming input and output parameters
	Programming of a new access code
	Access to display simulation
	Access to analogue output simulation
	Erasing of recorded alarms
	Tare suppression

Inputs

InPut Access to input programming submenu

tYPE Input type

U Voltage input

MA Current input

tEMP Temperature input

Pot Potentiometer input

rES Resistance input

Voltage input and current input **U** **MA**

CALib Choice of voltage caliber

0-10 Input 0 to 10 V (or -10/10V)

300 Input 0 to 300 V (or -300/300V)

0-0.1 Input 0 to 100 mV (or -100/100mV)

0-1 Input 0 to 1 V (or -1/+1V)

d.in Input down scale

F.in Input full scale

Funct Choice of processing function

LinEA. Linear

root Square root extraction

Li.SPE Special linearisation

nb Number of linearisation points

Axx Abscisse of a special linearisation point

Temperature input **tEMP**

CAPt. Type of temperature sensor

Pt 100 Input RTD 100

tc Input thermocouple

tC - - Type of thermocouple

tc.CA Thermocouple K (see table page p13)

CJC Type of cold junction compensation

CJC-I Internal cold junction compensation

CJC-E External cold junction compensation

CJ-t Value of external cold junction compensation

dPt Input delta PT100

ni 100 Input NI100

t° Type of degrees

°C Degree Celcius

°F Degree Fahrenheit

AdJuS. Input shifting

OFFSE. Offset shifting

d.diSP Shift display down scale slope and offset

AdJ.Lo Adjust display down scale

F.diSP Shift display full scale slope and offset

AdJ.Hi Adjust display full scale

Potentiometer and resistance input **Pot** **rES**

d.in Input down scale

F.in Input full scale

Funct Choice of processing function

LinEA. Linear

Li.SPE Special linearisation

nb Number of linearisation points

Axx Abscisse of a special linearisation point

LOGIC inputs

tor	Access to LOGIC inputs programming submenu
tor 1	Programming of LOGIC input 1
tor 2	Programming of LOGIC input 2
Point	Function decimal point moving
- - . -	-Decimal point position
CLr.M	Function erase min. and max.
HoLd	Function hold display
tArE	Function Tare

Display

diSPL.	Access to display programming submenu
Point	Choice of decimal point position
- - . -	-Decimal point position
d.diSP	Display down scale
F.diSP	Display full scale
bxx	Ordinate of a special linearisation point
Cut.oF	Cut-off programmable or not
rESOL.	Display resolution for temperature inputs
0.1⁰	Resolution 1/10 th degree
1⁰	Resolution degree
IntEG.	Integration indice

Display parameters

Pr.diS	Display features programming submenu
br.diG	Digits brightness setting (4 levels)
1111	Lowest brightness
4444	Highest brightness
br.bAr	Set bargraph and Leds brightness
1111	Lowest brightness
4444	Highest brightness
L.dIG	Last digit (LSB)
On	Last digit in service
OFF	Last digit enforced to 0
nuLL	Erasing of insignificant zeros
YES	Yes
no	No
d.bArG	display corresponding to 0% of bargraph
F.bArG	display corresponding to 100% of bargraph
LEdS	<i>Dedication of Led 5</i>
no	No dedication
tArE	Led lit if a tare has been entered
tor 1	Led 5 dedicated to indication of LOGIC input 1
LEd6	<i>Dedication of Led 6</i>
no	No dedication
tor 2	Led 6 dedicated to indication of LOGIC input 2
LEd7	<i>Dedication of Led 7</i>
no	No dedication
rS	Led lit in case of RS transmission
LEd8	<i>Dedication of Led 8</i>
no	No dedication
AdJuS.	Led lit when an input shifting has been entered (temperature input only)

Analogue output

Out.U	Access to voltage output programming submenus
Out.MA	Access to current output programming submenu
d.out	Analogue output down scale
F.out	Analogue output full scale
dO.diS	Access to the display corresponding to output down scale
FO.diS	Access to the display corresponding to output full scale

Digital output

JbuS	Access to RS output programming submenu
SLAuE	Slave number
bAud	Baud rate
1200	Possible rates
19200	Possible rates
dELAY	Delay before any answer
On	75ms delay
OFF	20ms delay

Relay outputs : x : 1 to 4

rELAY	Access to relay outputs programming submenu
rEL.x	Access to relay X programming
AL.x	Enable relay output 1
On	Enable
OFF	Disable
ModEx	Relay x function mode
1 1	Mode setpoints
1 1	Mode window
SPx	Value of setpoint in mode setpoint
SPx.1	Value of 1st setpoint in mode window
SPx.2	Value of 2nd setpoint in mode window
HYSt.x	Hysteresis value in display points
tiME.x	Delay on relay X

LEdx	Programming of the led associated with the relay
On	Led lit when relay is enabled (coil supplied)
OFF	Led still when relay is enabled (coil supplied)
MEM.x	Alarm x recording
YES	Recording
no	No recording
MESSx	Alarm message
YES	Message
no	No message

Safeties

SECU	Access to safeties programming submenu
rUPt	Programming of sensor rupture safety
CAPt.	Disconnect sensor rupture (or not)
OFF	Enable disconnection
On	Disable disconnection
rELX	State of relay X in case of sensor rupture
OFF	No sensor rupture associated with relay
LO	Relay disabled in case of sensor rupture (coil not supplied)
H I	Relay enabled in case of sensor supply (coil supplied)
out.U	Output return value (or not)
or	in case of sensor rupture
YES	Return value required
no	No return value
rEPLi	Return value
diAG.	Self diagnosis safety programming
rELX	State of relay X in case of error self diagnosis
OFF	No self diagnosis associated with relay
LO	Relay disabled in case of error self diagnosis (coil not supplied)
H I	Relay enabled in case of error self diagnosis (coil supplied)

☐ out.U ☐ out.MA Return value (or not) on the output
 or
☐ YES Return value required ☐ no No return value
☐ rEPLi Return value

Saving configuration

☐ SAuE Configuration recording
☐ YES Recording ☐ no No recording

Reading of instrument internal features

☐ About Access to internal features reading submenu
☐ d75M Instrument type : DGN 75 U, DGN 75 T, DGN 75 M
☐ n° ☐ A0006 Identification numbers
☐ PrOG Programme version
☐ 06.00 Programme version number
☐ OPTiO. Option code
☐ Ar - - Option code value
☐ Err. Self diagnosis error
☐ 0000 Type of error
☐ CH.SuM Check sum display
☐ FC4E Check sum value

Further functions

☐ InF. Display minimum value
☐ SuP. Display maximum value
☐ CLr.M Erase min. and max.

Error messages

☐ Err.1 Set value out of range
☐ OPEn Sensor rupture
☐ 2000 Flashing measure : measure in overload
☐ OL Displayable value overstepping
☐ - - - Input lower or upper electrical overstepping
☐ Er.xxx Error self diagnosis

9. ANNEXE : MODBUS

9.1 Table of modbus addresses

Address		Format	nb of words
200	Analogue output value in μ A (mA output) in mV (10V output)	double integer	2
202	Minimum value of displayed value	double integer	2
204	Maximum value of displayed value	double integer	2
206	Displayed value	double integer	2
208	Direct measure	double integer	2
290	State of relay 1	integer	1
291	State of relay 2	integer	1
292	State of relay 3	integer	1
293	State of relay 4	integer	1

• Direct measure :

Value without scale factor for inputs 100 mV, 1V, 10V, 300V, 20 mA :

- in mV for input 10V
- in $1/10^{\text{th}}$ of mV for input 1V
- in μ A for input mA
- in $1/100^{\text{th}}$ of mV for input mV
- in $1/100^{\text{th}}$ of V for input 300V

Resistance value in $1/100^{\text{th}}$ Ω for NI100 and Pt100

Value of hot sensor temperature in $1/10^{\text{th}}$ of degree for Δ Pt100


Resistance value

- in $1/100^{\text{th}}$ Ω for resistance input 0-400 Ω
- in $1/10^{\text{th}}$ Ω for resistance input 0-2000 Ω
- in Ω for resistance input 0-8000 Ω

Value in μ V for input thermocouple

Value in $1/100^{\text{th}}$ of % for input potentiometer


• State of relays :



• Displayed measure :

The displayed measure value is recovered without decimal point. To read the decimal point value, read the word at address 120.

Address 120 :




Decimal point location from 1 to 4 (version 10 000 points)
from 0 to 4 (version 100 000 points)

- 0 : Display with 4 decimals (version 100 000 points)
- 1 : Display with 3 decimals
- 2 : Display with 2 decimals
- 3 : Display with 1 decimals
- 4 : Display with 0 decimals


9.2 Description of born modbus functions :

Reading of N words : Function n°3

Request pattern :




Response pattern :




Writing of N words : Function N°16

Request pattern :




Response pattern :




Writing of 1 word : Function N°6 :


Request pattern :



Response pattern :



Exception pattern :




Values of error codes :

- 1 : Function code unknown
- 2 : Address incorrect
- 3 : Data incorrect
- 9 : Writing impossible


9.3 Reading in double integer format :

Example : Reading of displayed measure


Request :



• Response with positive measure :





Value of measure :




$$\begin{aligned}\text{Measure} &= \text{byte 3} \times 256^3 + \text{byte 4} \times 256^2 + \text{byte 1} \times 256 + \text{byte 2} \\ &= 0 \times 256^3 + 0 \times 256^2 + 19 \times 256 + 136 \\ &= 5000\end{aligned}$$

Reading of address 120 => decimal point = 2
=> displayed measure 50.00

• Response with negative measure :




Sign : 1 negative : inversion of bits and add 1.



$$\begin{aligned}\text{Measure} &= -(\text{byte 3} \times 256^3 + \text{byte 4} \times 256^2 + \text{byte 1} \times 256 + \text{byte 2}) \\ &= -(0 \times 256^3 + 0 \times 256^2 + 19 \times 256 + 136) \\ &= -5000\end{aligned}$$

Reading of address 120 => decimal point = 2
=> displayed measure -50.00

9.4 CRC 16 calculation algorithm :



Note 1 : ⊕ = exclusive or.

Note 2 : POLY = A001 (hex).

Note 3 :

The CRC16 calculation applies to all bytes in the pattern (except CRC16).

Note 4 :

Caution ! In the case of CRC 16, the 1st sent byte is the LSB.

Example : Pattern 1-3-0-75-0-2 CRC16 = 180-29 (values are decimal).