



MR ICI 40-200

CONTENT

Augmented Reality (AR) - Digital meets real	2
3D preview of MR ICI 40-200	3
Integrate Rossi catalog inside your CAD System	4
2D derivations and Bill-Of-Material (BOM)	5
Technical drawings	6
Technical data	7
Get a free E-Learning training for Rossi catalog	8



3Dfindit


powered by  CADENAS



MR ICI 40-200

AR

Augmented Reality, often shortened to AR, is a technology that blends digital information into the real world. For more information, please click [here](#) or directly try yourself by scanning the QR code with your phone.



Please scan the QR code above and open on AR-enabled device.

There is a possibility that the configuration will fail. If that happens, please try a different product.




3Dfindit

powered by  CADENAS



MR ICI 40-200

3D view



HOW TO ACTIVATE 3D?

To activate the interactive 3D view in Acrobat Reader, you need to select, at the top of the page, **Options** and then **Trust this document**

Zoom

Moves you toward or away from objects in the scene when you drag vertically. You can also zoom with the hand tool by holding down Shift as you drag.

Pan

Moves the model vertically and horizontally only. You can also pan with the hand tool: Ctrl-drag.

Rotate

Turns 3D objects around relative to the screen. How the objects move depends on the starting view, where you start dragging and the direction in which you drag.



3Dfindit


powered by  CADENAS



MR ICI 40-200

CAD plugins

With our CAD integrations, you can use 3Dfindit directly in your CAD system and make your work easier with additional comfort functions, such as replacing a part and many more.



To the plugins




3Dfindit

powered by  CADENAS




MR ICI 40-200

2D derivation



ISO view



Bill-Of-Materials

N°	Description	Amount
1	G_MR_ICI_100_UO3A_24x200_31.4_B3_SM	1



3Dfindit

powered by



CADENAS



MR ICI 40-200

Technical drawings



3Dfindit

powered by  CADENAS



MR ICI 40-200

Technical data

A1 (Machine)	MR
A2 (Train of gears)	ICI
A3 (Size)	100
A4 (Design)	UO3A
A5 (Motor coupling)	24x200
A6 (Transmission ratio)	31.40
A7 (Mounting position)	B3
A8 (Low speed shaft)	No
A9 (B5 flange)	No
A10 (Backstop device)	No
A12 (Shaft mounting arrangements)	No
A15 (Washer/Protection)	No
A17 (NEMA C-Face adapter)	No
A18 (Motor type)	No motor
A19 (Motor size)	-
A20 (Terminal box position)	-
A21 (Power)	-
A22 (Poles)	-
A32 (Frequency)	-
A23 (Directive)	-
A24 (Efficiency)	-
A25 (Motor mounting position)	-
A26 (Second shaft end)	-
A27 (Cooling)	-
A28 (Encoder)	-
A29 (Drip proof cover)	-
A30 (Release lever)	-



MR ICI 40-200

E-Learning

Discover free training for 3Dfindit, the search engine for engineers, designers, and architects. Our 30 to 50-minute interactive courses provide you with comprehensive knowledge about the platform. Upon successful completion, you will receive a certificate. Start your first course now and master 3Dfindit!

**Become an Expert of
Digital Engineering**



3Dfindit

**Boost your career
and get ready
for Industry 4.0!**

[Learn more](#)

[Start course](#)