




PREKLOPKE BEZ "0" POLOŽAJEM - KUT ZAKRETA 90°



1 pole
1 *polna*
2 pole
2 *polna*
3 pole
3 *polna*
4 pole
4 *polna*
5 pole
5 *polna*
6 pole
6 *polna*
7 pole
7 *polna*
8 pole
8 *polna*
9 pole
9 *polna*
10 pole
10 *polna*
11 pole
11 *polna*
12 pole
12 *polna*

54	1
55	2
56	3
69	4
70	5
71	6
72	7
73	8
74	9
62	10
43	11
44	12



1	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X
2	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X

54

55

56

69

70

71

72

73

74

62

43

44