



Purge

PTS

Air purge level transmitter unit with 1/2 threshold relays

Air purge; connection to a 20PSI air instrumentation, (137,895 kPa)

Undecal socket mounting into DIN-rail

Zero and Span frontal trimmers adjustment n

Working temperature -10, +50°C

Version	
A	IP20, n.1 threshold relay
B	IP20, n.2 threshold relays
Z	Special
Power supply	
0	24Vac 50/60 Hz
1	115Vac 50/60 Hz
2	230Vac 50/60 Hz
4	24Vdc
9	Special
Output	
A	4÷20mA
B	0÷10V
Z	Special
Measure range	
2	0÷1000mm H ₂ O, (0÷9,80665kPa)
4	0÷5000mm H ₂ O, (0÷4,903325kPa)
9	Special max 20.000mm H ₂ O, (0÷196,133kPa)
Accessories	
A	None
B	Socket and fixing spring
Z	Special

