


Drawings

ZR802G Zirconia Oxygen/Humidity Analyzer, Converter


SD 11M12G01-01EN




Weight: Approx. 5 kg

Unless otherwise specified, differences in the dimensions are specified as: General tolerance = $\pm$ (Criteria of tolerance class IT18 in JIS B0401-1998)/2.

□ Hood (option code /H)




□ ZR402G Replacement Wall Mounting Bracket (option code /BR)



Unless otherwise specified, differences in the dimensions are specified as: General tolerance = $\pm$ (Criteria of tolerance class IT18 in JIS B0401-1998)/2.

WIRING CONNECTIONS



*1: The ground wiring of the converter should be connected to either the protective ground terminal in the equipment or the ground terminal of the converter case.

Ground to earth, ground resistance: 100 Ω or less.

*2: Option (Temperature or Pressure transmitter provide by user) for humidity measurement.

*3: Suffix Code "E"

*4: Suffix Code "M"