


SR13 MR V 32...81

3D view



HOW TO ACTIVATE 3D?

To activate the interactive 3D view in Acrobat Reader, you need to select, at the top of the page, **Options** and then **Trust this document**

Zoom

Moves you toward or away from objects in the scene when you drag vertically. You can also zoom with the hand tool by holding down Shift as you drag.

Pan

Moves the model vertically and horizontally only. You can also pan with the hand tool: Ctrl-drag.

Rotate

Turns 3D objects around relative to the screen. How the objects move depends on the starting view, where you start dragging and the direction in which you drag.

Augmented Reality (AR) - Digital meets real


Augmented Reality, often shortened to AR, is a technology that blends digital information into the real world.
For more information, please click here or directly try yourself by scanning the QR code with your phone.

SCAN ME




SR13 MR V 32...81

2D derivation



ISO view



Bill-Of-Materials

N°	Description	Amount
1	SR13 MR V 80 UO3A 50 P07 24x50	1



Technical drawings



SR13 MR V 32...81

Technical data


GRANDEZZA (Gear reducer size / mm)	80
ESECUZIONE (Gear reducer design)	UO3A
I (Transmission ratio)	50
FL (Flange)	P07
ESTR (High speed shaft extruder)	24x50
AL (Standard / solid low speed shaft)	No
ALCM (Design for hollow low speed shaft)	No
FB5 (B5 flange)	No
RALC (Hollow low speed shaft washer / protection)	No
SFP (Shaft-mounting arrangements)	No



SR13 MR V 32...81

CAD plugins

With our CAD integrations, you can use 3Dfindit directly in your CAD system and make your work easier with additional comfort functions, such as replacing a part and many more.



To the plugins