




O-RING
P/N P11000-113
REPLACES P/N 12-6227N011
QTY: 2



O-RING 90 SHORE
P/N P11003-110
REPLACES P/N 12-6227N008S
QTY: 2




GASKET
P/N 11-5028N000
REPLACES P/N 10-450-28
QTY: 1



TEFLON BACK UP
P/N P11227-010
REPLACES P/N 12-8774T005
QTY: 2



O-RING
P/N P11000-010
REPLACES P/N 12-6227N005
QTY: 1



PISTON BUMPER
P/N 11-5051P000
REPLACES P/N 10-450-51
QTY: 1



RETAINING RING
P/N P10202-050
REPLACES P/N 12-R050S000
QTY: 1



HELICAL SPRING LOCK WASHER
P/N P10212-025
REPLACES P/N 12-5001C407
QTY: 1

1. COMPONENT PICTURES ARE NOT TO SCALE



SC HYDRAULIC ENGINEERING CORPORATION
BREA, CA 92821

HYDRAULIC REPAIR KIT P/N 11-5148N250
REPLACES HYDRAULIC REPAIR KIT P/N 10-450-148-25

REV: B, 12/09/2021.