

HellermannTyton

SERVICE PARTS LIST

EVO9i APPLICATION TOOL		PREVIOUS BULLETIN	REVISION	DATE OF RELEASE	
ITEM NO.	110-88001	STARTING SERIAL NUMBER: DA1000000	—	00	2024/02/26




FIG	PART NO.	QTY.	DESCRIPTION OF PART	FIG	PART NO.	QTY.	DESCRIPTION OF PART
1	110-70044	1	Rotating Cam	28	110-80076	1	Inner Tension Spring
2	110-70049	1	Tension Shaft	29	110-80044	1	Blade Link Attachment Pin
3	110-70048	1	Twist Off Calibration Cap	30	110-80045	1	Inner Link Attachment Pin
4	110-70022	1	Blade Return Assist Spring	31	110-80046	1	Upper Short Link Attachment Pin
5	110-70043	1	Fixed Cam	32	110-80049	1	Cutoff Cam Shaft
6	110-70054	1	Tension Spring Thrust Bearing	33	110-88018	1	Needle Roller (M3x27.8)
7	110-70072	1	Locking Latch Return Spring	34	110-88019	1	Needle Roller (M4x15.8)
8	110-70073	1	Tension Knob Detent Spring	35	110-77020	1	Needle Roller (M4x27.8)
9	110-70127	4	Rear Roller	36	110-88026	1	Needle Roller (M4x19.8)
10	110-70138	1	Tension Calibration Nut	37	110-88020	2	Needle Roller (M4x27.8)
11	110-80005	1	Pawl Link Assembly	38	-	-	Serial Number Label**
12	110-80063	1	Trigger Boot (Grey)	39	110-88021	1	Tension Knob
13	110-80019	1	Pinion	40	110-88023	1	Locking Latch
14	110-80022	1	Short Link - Standard Span	41	110-88022	1	Housing Set Base and Cover
15	110-80023	1	Cutoff Cam	42	-	-	EVO9i Label Set**
16	110-80027	1	Blade Link	43	110-70082	1	Star Drive Pan Head M3x1.5x10mm
17	110-80018	1	Nosepiece	44	110-77016	4	BHCS Star Drive M3x0.5x10mm w/ Vibratite
18	110-80028	1	Trigger Stamping	45	110-77015	1	PHMS Star Drive M2.5x0.45x6mm
19	110-80029	2	Inner Link	46	110-70059	2	E-Style Retaining Ring (DIN)*
20	110-80030	2	Intermediate Link	47	110-80054	2	E-Style Retaining Ring (DIN)*
21	110-80031	1	U-Bracket	48	110-70051	1	Ball Bearing
22	110-80036	1	Pawl Cover				
23	110-80037	1	Blade				
24	110-80038	1	Hang Hook				
25	110-80042	1	Pinion Spring				
26	110-80073	1	Outer Tension Spring				
27	110-80074	1	Trigger Return Spring				

*If tool experiences e-clip failure or loss, replace entire pin and e-clip assembly. Otherwise user may procure JIS 2.3 e-ring from external source

**Non Serviceable Part

***Replacement Housing assemblies include 110-88018 (qty 1); 110-77020 (qty 1) and 110-88020 (qty 1) molded into the housing. In an event where only the pin replacement is needed they may be ordered separate.